# Westhertzanon Assistance Program

### Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/18018UE-1820/1

Work Order Type: Weatherization Audit Name: 18018UE-1820

**CLIENT INFORMATION** 

Client Name: Address:

**Client ID:** 18018UE-1820

<u>AGENCY INFORMATION</u>

Alt. Client ID: Washington

Agency: Upper East Tennessee Human Development Agency Agency Phone: 246-6180

Address: 301 Louis Street Fax:

Agency Contact: Hoard, Howard Work Phone: (423) 246-6180

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

Client live in 1940 + home Certified rennovator

House is massonite with shingle roof

added on porch

Front door missing glass and back door the lockset out and w/s destoyed.

SF 768

No floor insulation, m no wall insulation, hardly no attic insulation (1")

Missing 5 ilight and plug in covers.

Front room need floor repair has hole at entrance looking to repair 100sq. Ft.

PA. 3989 @ 49.7 and target 2792.3

Client Name:
Client ID: 18018UE-1820
Alt. Client ID: Washington

Work Order (Bid Form)

Work Order Name: WO/18018UE-1820/1 Report Run On: 3/30/2012 DOE Weatherization Assistant Version 8.6.0

Page 1 of 9

#### **Measures**

/	Measure 1 DWF	l Tank Insulation			Componen	ts		ı	nspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	DHW Tank Insulation	Each	1					
1	Hot Water Equip	DHW Tank Insulation	Each	1					
0	Other Detail								
				Measur	re Sub Total:			Sub Total:	
	Field Notes:								
/	Measure 2 Attic	: Ins. R-38			Componen	ts A1		ı	nspected
			dina to TV	VFG P	-	<i>t</i> s A1		,	nspected
		: Ins. R-38 in living room build accor	ding to TV	VFG P	-			I Actual	Inspected
C			ding to TV	VFG P	g 116		Qty		Inspected
C	omment Access i	in living room build according to the composition of the composition o	-		g 116 Estimated	1	Qty	Actual	
<i>C</i> :	omment Access i	in living room build accor	Units	Qty	g 116 Estimated	1	Qty	Actual	
<i>C</i> :	omment Access i	Description / Comment Attic Insulation - Blown Cellulose - R-38 Attic Insulation - Blown	Units	Qty	g 116 Estimated	1	Qty	Actual	
<b>C</b> (	omment Access in Material / Labor Insulation	Description / Comment  Attic Insulation - Blown Cellulose - R-38	<i>Units</i> SqFt	<b>Qty</b> 100	g 116 Estimated	1	Qty	Actual	
<b>C</b> 4 1	omment Access in Material / Labor Insulation	Description / Comment Attic Insulation - Blown Cellulose - R-38 Attic Insulation - Blown	<i>Units</i> SqFt	<b>Qty</b> 100	g 116 Estimated	1	Qty	Actual	
# 1	omment Access i  Material / Labor  Insulation  Labor	Description / Comment Attic Insulation - Blown Cellulose - R-38 Attic Insulation - Blown	<i>Units</i> SqFt	<b>Qty</b> 100	g 116 Estimated	1	Qty	Actual	
# 1	omment Access i  Material / Labor  Insulation  Labor	Description / Comment Attic Insulation - Blown Cellulose - R-38 Attic Insulation - Blown	<i>Units</i> SqFt	<b>Qty</b> 100	g 116 Estimated	1	Qty	Actual	
<b>C</b> 4 1	omment Access i  Material / Labor  Insulation  Labor	Description / Comment Attic Insulation - Blown Cellulose - R-38 Attic Insulation - Blown	Units SqFt SqFt	<b>Qty</b> 100	g 116 Estimated	1		Actual	
# 1 1 O	omment Access i  Material / Labor  Insulation  Labor	Description / Comment Attic Insulation - Blown Cellulose - R-38 Attic Insulation - Blown	Units SqFt SqFt	<b>Qty</b> 100	g 116  Estimated  Unit Cost	1		Actual Unit Cost	
# 1 1 O	omment Access i  Material / Labor Insulation  Labor  Other Detail	Description / Comment Attic Insulation - Blown Cellulose - R-38 Attic Insulation - Blown	Units SqFt SqFt	<b>Qty</b> 100	g 116  Estimated  Unit Cost	1		Actual Unit Cost	
# 1 1 O	omment Access i  Material / Labor Insulation  Labor  Other Detail	Description / Comment Attic Insulation - Blown Cellulose - R-38 Attic Insulation - Blown	Units SqFt SqFt	<b>Qty</b> 100	g 116  Estimated  Unit Cost	1		Actual Unit Cost	

	<i>Measure</i> 3 Ligh	ting Retrofits			LT4	4 Inspected			
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact Fl 13 Watt (Living Rm)	Each Lamp	4					
1	Labor	Compact Fl 13 Watt	Each Lamp	4					
2	Lighting	Compact Fl 15 Watt Flood (Bedroom)	Each Lamp	2					
2	Labor	Compact Fl 15 Watt Flood	Each Lamp	2					
3	Lighting	Compact Fl 13 Watt (Laundry Rm)	Each Lamp	2					
3	Labor	Compact Fl 13 Watt	Each Lamp	2					
4	Lighting	Compact Fl 13 Watt (Bath)	Each Lamp	1					
4	Labor	Compact Fl 13 Watt	Each Lamp	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 4 DW Comment	/H Pipe Insulation			Componen				Inspected
# Matarial / Labor	December / Comment	Unita		Estimated	<del></del>		Actual	Total
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor	DHW Pipe Insulation	Each	1					
1 Insulation	DHW Pipe Insulation	Each	1					
Other Detail			1			1		
			Measur	e Sub Total:		,	Sub Total:	
	or Ins. R-19 on 24" OC and has 2" x 4"			Componen  Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	700		- Total	4.9		70.07
1 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	700					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								

Measure 6 Wa Comment	II Insulation			Componen  Estimated	ts WL4		Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	248.7					
1 Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	248.7					
Other Detail								
			Measure	Sub Total:		,	Sub Total:	
Measure 7 Wa	II Insulation			Componen	ts WL3			Inspected
		11.20		Estimated			Actual	<b>-</b>
# Material / Labor  1 Insulation	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	<b>Units</b> SqFt	<b>Qty</b> 148.0	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	148.0					
Other Detail								
			Measure	Sub Total:			Sub Total:	
Field Notes:								

	II Insulation			Componen	ts WL1			Inspected
Comment				Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	160.3					
1 Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	160.3					
Other Detail								
			Measur	Sub Total:			Sub Total:	
Field Notes:			measure					
	II Insulation			Componen				Inspected
Measure 9 Wal		Units		Estimated		Qtv	Actual	
Measure 9 Wal Comment # Material / Labor	Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled	<i>Units</i> SqFt		-		Qty		Inspected Total
Measure 9 Wall Comment # Material / Labor 1 Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated		Qty	Actual	
Measure 9 Wall Comment # Material / Labor 1 Labor	Description / Comment  Wall Insulation - Blown Cellulose - 2x4 Filled  Wall Insulation - Blown	SqFt	<b>Qty</b> 248.8	Estimated		Qty	Actual	
Measure 9 Wall Comment  # Material / Labor 1 Labor 1 Insulation	Description / Comment  Wall Insulation - Blown Cellulose - 2x4 Filled  Wall Insulation - Blown	SqFt	<b>Qty</b> 248.8	Estimated		Qty	Actual	
Measure 9 Wall Comment  # Material / Labor 1 Labor 1 Insulation	Description / Comment  Wall Insulation - Blown Cellulose - 2x4 Filled  Wall Insulation - Blown	SqFt	<b>Qty</b> 248.8 248.8	Estimated			Actual	

#### **Measure 10 Storm Windows**

## **Components** WD1,WD2,WD6,WD 3,WD4,WD5

Inspected

Ī	Comment								
#	Material / Labor	Description / Comment	Units	Qty	Estimate Unit Cost	Total	Qty	Actual Unit Cost	Total
	Windows	Storm Window	SqFt	60.09	Unit Cost	IOtal	Qty	Unit Cost	Total
'	Willdows	Storm window	SqFt	00.09					
1	Labor	Storm Window	Each	2					
2	Windows	Strom Window	SqFt	33.33					
2	Labor	Storm Windws	Each	2					
3	Windows	Storm Window	SqFt	33.33					
3	Labor	Storm Windows	Each	1					
4	Windows	Storm Window	SqFt	33.33					
4	Labor	storm Windows	Each	2					
5	Labor	Storm Windows	Each	1					
5	Windows	Storm Windowa	SqFt	33.33					
6	Windows	Broke glass	Each	2					
6	Labor	to install new glass (front and side window)	Each	2					
7	Windows	Glaze all (8) windows	Each	8					
7	Labor	Install glaze on (8) windows	Each	8					
C	Other Detail								
				Measure	e Sub Total:			Sub Total:	
	Field Notes:								

Client Name: Client ID: 18018UE-1820 Alt. Client ID: Washington

	Measure 11 Fix ( (Bas	Other Problems ement/Crawlspace)			Componen	ts		1	nspected
C	Comment Replace	flooring in living. Has ho	ole and a p	iec of	wood over h Estimated	-	oosed.	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	Labor	SqFt	100					
1	Health and Safety	Equipment	SqFt	100					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
		Viring Problems (Walls light nd switch covers	5)		Componen				nspected
#	Material / Labor	Description / Comment	Units	Oti/	Estimated Unit Cost	Total	Otv	Actual Unit Cost	Total
	Health and Safety	Description / Comment  Equipment	Each	<b>Qty</b> 5	Unit Cost	Total	Qty	Unit Cost	l Otal
1	Labor	Labor	Each	5					
C	Other Detail						1		
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 13 Smo Comment	ke Detector is Needed			Componen	its			Inspected
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Smoke detector	Each	1					
1 Labor	Labor	Each	1					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Measure 14 Vapo	or Barrier Needed ement/Crawlspace)			Componer	nts			Inspected
Comment	,			<b>-</b>				
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1 Labor	Labor	SqFt	700					
1 Health and Safety	Basement / crawlspace vapor barrier	SqFt	700					
Other Detail			1			7		
						]	Sub Total:	
Field Notes:			weasur	e Sub Total:			oub rotal.	